

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

1/35




Fig. 1

FIG. 1

FIG. 2




Fig. 2




Fig. 3




Fig. 4

3/35




Fig. 4A




Fig. 12A

4/35




Fig. 5




Fig. 6




Fig. 7




Fig. 8

003544 043001

5/35

Fig. 9




Fig. 10




Fig. 12





Fig. 11



6/35

FIG. 13




Fig. 13

Fig. 14




Fig. 16






Fig. 15



7/35

Fig. 17



8/35

FIG. 18




Fig. 18




Fig. 19

Fig. 20

9/35





Fig. 21



10/35

80




Fig. 23A




Fig. 23







Fig. 22





71

11/35



0933545.042001

12/35



000240" 54595850

13/35




Fig. 28




Fig. 29







Fig. 29A

000240" 54582850

14/35



15/35

FIG. 32(a)




Fig. 32(a)

Fig. 32(b)




FIG. 33





Fig. 33

16/35

Fig. 34



17/35





Fig. 35

FIG. 35

99

18/35

100240" 34595250



20/35

FIG. 42




Fig. 43




Fig. 44




Fig. 45




Fig. 46





Fig. 47



21/35

FIG. 48




Fig. 48




Fig. 49




Fig. 50




Fig. 51

22/35

FIG. 52




Fig. 53




Fig. 54




Fig. 55







Fig. 56



23/35



00240" 54585850

24/35









FIG. 59

Fig. 62

$$25/35$$


26/35



21/35

Fig. 67




Fig. 68






Fig. 69






28/35




Fig. 70



29/35



30/35



003354 04001

32 / 35








Fig. 78

09838545 042001

31/35



33/35



34/35

FIG. 82




Fig. 83




Fig. 82

35/35




Fig. 84




Fig. 85

09638543 043001
T00240 6458880